

CLASSIFIED MESSAGE

ROUTING

SECRET

1	D/Leah	9	CD
2		10	MP
3		11	RB
4	OP	12	
5		13	
6		14	
7	Intel	15	
8	D/FA	16	

50X1

ROUTINE

OXCAR T

IN 54956

0123Z 18 DEC 63

TO DIRECTOR

FROM KWCABLE

ACTION: OSA 1-15

INFO :

TOR: 0244Z 18 DEC 63

TO ADIC

INFO

CITE

CABLE 3112

OXCAR T MEDICAL

50X1

FOLLOWING COMMENTS CONCERN SUIT FLIGHT OF [] IN
FRONT SEAT OF ARTICLE 124, 17 DEC 63. TIME IF FLIGHT 1:13.
TIME IN SUIT 2:25.

1. PILOT HAD FOGGING OF VISOR DURING FLIGHT. MALFUNCTION IN TENSION OF HEATER CONTACT SPRING WHEN MOVING HELMET DURING POST FLIGHT. MODIFIED "D" RING DIFFICULT TO GRASP WITH SUIT PRESSURIZED.

2. [] IN BACK SEAT, NO SUIT, EVALUATED AN
ADJUSTABLE AIR INFLATED SEAT POD. ALTHOUGH DIFFICULTY TO
REGULATE WITH VARYING CABIN ALTITUDES POD WAS COMFORTABLE.

50X1

END OF MESSAGE

DOCUMENT NO. _____
NO CHANGE IN CLASS. ☒
☐ DECLASSIFIED
CLASS. CHANGED TO: TS S C 2011
NEXT REVIEW DATE: _____
AUTH: HR 10-2
DATE: 16/9/81 REVIEWER: 064540

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.